Figure 23 - Dwg. 65 - Prelim Treatment Works - East Elev.tif




Figure 24 - Dwg. 68 - Prelim Treatment Works - Railing Details Settling Basins.tif

Figure 25 - Dwg. 111 - Purification and Pumping Works - Special Lighting Fixtures.tif

08 Appendix II: Photo Index

Recordation of the Head House, Trestle and Settling Basins 1-4 for Meander Water, Mahoning Valley Sanitary District (MSVD) Mineral Ridge, Ohio

Name of Property: Mahoning Valley Sanitary District

City: Mineral Ridge, Ohio

County: Trumbull State: Ohio

Name of Photographer: Chambers, Murphy & Burge/Ashley Cramer

Date of Photographs: June 2011

Location of Original Files: Chambers, Murphy & Burge Restoration Architects

43 E. Market St., Suite 201, Akron OH 44308

Number of Photos: 55

01	West Elevation, View of West Elevation, Camera pointing East
02	West Elevation, View of West Elevation, Camera pointing Southeast
03	Northwest Corner, View of Northwest corner and Basin #4, Camera pointing Southeast
04	West Elevation, View of West Elevation and Basin #4, Camera pointing South
05	West Elevation, View of Basin #4, Camera pointing East
06	West Elevation, View of Basin #4 and Trestle, Camera pointing Southeast
07	West Elevation, View of Trestle, Camera pointing Southeast
80	Southwest Corner, View of Southwest corner and Basin #1, Camera pointing Northeast
09	West Elevation, View of Basin #1, Camera pointing East
10	West Elevation, View of Basin #1, Camera pointing Southeast.
11	South Elevation, View of Basin #1 and Trestle at Head House, Camera pointing North
12	South Elevation, Arial view of buildings, Camera pointing North
13	South Elevation, Arial view of buildings, Camera pointing North
14	South Elevation, View of Head House and Trestle, Camera pointing Northeast
15	West Elevation, View of Basin #1 and Trestle, Camera pointing North
16	Southeast Corner, View of Head House and Trestle, Camera pointing North
17	East Elevation, View of Head House and Trestle, Camera pointing West
18	East Elevation, View of Head House and Trestle, Carnera pointing West
19	East Elevation, View of Head House, Camera pointing East
20	North Elevation, View of Head House, Camera pointing South
21	East Elevation, View of Trestle, Camera pointing South
22	East Elevation, View of Head House, Camera pointing West
23	North Elevation, View of Head House, Camera pointing West
24	North Elevation, View of Basin #4, Camera pointing South

08 Appendix II: Photo Index


Recordation of the Head House, Trestle and Settling Basins 1-4 for Meander Water, Mahoning Valley Sanitary District (MSVD) Mineral Ridge, Ohio

25	South Elevation, Arial view of Buildings, Camera pointing North
26	East Elevation, View of door in Trestle, Camera pointing South
27	Top of Tower, View of Basin #4, Camera pointing Northwest
28	Top of Tower, View of Roof over Basin #3, Camera pointing Northeast
29	Top of Tower, View of Basin #1, Camera pointing Southwest
30	Top of Tower, View of Basin #1 and Roof over Basin #2, Camera pointing South
31	Inside of Head House, Building Plaque, Camera pointing East
32	Inside of Head House Entry Level, View of Recarbination Flow Meter, Camera pointing East
33	Inside of Head House Entry Level, View of Rapid Mixer, Camera pointing Southwest
34	Inside of Head House Entry Level, View of Rapid Mixer, Camera pointing South
35	Inside of Head House Entry Level, Camera pointing West
36	Inside of Head House Entry Level, Camera pointing East
37	Inside of Head House Entry Level, View of Switchboard, Camera pointing North
38	Inside of Head House, View of Switchboard, Camera pointing South
39	Inside of Head House, View of Switchboard, Camera pointing South
40	Inside Mixing Chambers Building, Camera pointing South
41	Inside Mixing Chambers Building, Camera pointing South
42	Inside Mixing Chambers Building, Flocculator Drive Mechanisms (motors), Camera pointing Southwest
43	Inside Mixing Chambers Building, Flocculator Drive Mechanisms (motors), Camera pointing South
44	Inside Settling Chamber Building, View of Settling Basin #3, Camera pointing Southwest
45	Inside Settling Chamber Building, View of Settling Basin #3, Camera pointing Northwest
46	Inside Mixing Chambers Building, View of Settling Basin #2, Camera pointing Southeast
47	Inside Mixing Chambers Building, Camera pointing North
48	Inside Settling Chamber Building, View of Settling Basin #2, Camera pointing East
49	Inside Mixing Chambers Building, View of Settling Basin #3, Camera pointing Northeast
50	Inside of Settling Basin Building, View of Settling Basin #2, Camera Southwest
51	Inside Settling Chamber Building, Camera pointing North
52	Inside Settling Chamber Building, View of Settling Basin #2, Camera pointing


08 Appendix II: Photo Index

Recordation of the Head House, Trestle and Settling Basins 1-4 for Meander Water, Mahoning Valley Sanitary District (MSVD) Mineral Ridge, Ohio

53	Inside Settling Chamber Building, View of Settling Basin #2, Camera pointing West
54	Inside of Car Shed, View of top of Trestle, Camera pointing East
55	Inside of Car Shed, View of Train Car, Camera pointing Southwest



Mahoning Valley Sanitary District SETTLING SETTLING BASIN #3 BASIN #4 SETTLING SETTLING BASIN #1 BASIN #2 N Drawings Not to Scale Title: Photo Key First Floor Plan Chambers, Murphy & Burge 43 E. Market St. Suite 201 Location: Mineral Ridge, Ohio Akron, Ohio 44308 Skeah Number: Job No. 11-17 Chambers, Murphy & Burge Phone: (330) 434-9300 PK-02 Fax: (330) 434-9331 Date: August 2011





01. OH_Trumbull_MahoningValleySanitaryDistrict_0001.tif



02. OH_Trumbull_MahoningValleySanitaryDistrict_0002.tif



 $03. \ OH_Trumbull_MahoningValleySanitaryDistrict_0003.tif$



 $04. \ OH_Trumbull_MahoningValleySanitaryDistrict_0004.tif$



05. OH_Trumbull_MahoningValleySanitaryDistrict_0005.tif



06. OH_Trumbull_MahoningValleySanitaryDistrict_0006.tif



07. OH_Trumbull_MahoningValleySanitaryDistrict_0007.tif



08. OH_Trumbull_MahoningValleySanitaryDistrict_0008.tif



 $09. \ \ OH_Trumbull_MahoningValleySanitaryDistrict_0009.tif$



10. OH_Trumbull_MahoningValleySanitaryDistrict_0010.tif



11. OH_Trumbull_MahoningValleySanitaryDistrict_0011.tif



12. OH_Trumbull_MahoningValleySanitaryDistrict_0012.tif



 $09. \ \ OH_Trumbull_MahoningValleySanitaryDistrict_0009.tif$



10. QH_Trumbull_MahoningValleySanitaryDistrict_0010.tif



13. OH_Trumbull_MahoningValleySanitaryDistrict_0013.tif



14. OH_Trumbull_MahoningValleySanitaryDistrict_0014.tif



15. OH_Trumbull_MahoningValleySanitaryDistrict_0015.tif



16. OH_Trumbull_MahoningValleySanitaryDistrict_0016.tif





18. OH_Trumbull_MahoningValleySanitaryDistrict_0018.tif



19. OH_Trumbull_MahoningValleySanitaryDistrict_0019.tif



 $20. \ OH_Trumbull_MahoningValleySanitaryDistrict_0020.tif$



21. OH_Trumbull_MahoningValleySanitaryDistrict_0021.tif



 ${\bf 22. \ OH_Trumbull_MahoningValleySanitaryDistrict_0022.tif}$



23. OH_Trumbull_MahoningValleySanitaryDistrict_0023.tif



24. OH_Trumbull_MahoningValleySanitaryDistrict_0024.tif



25. OH_Trumbull_MahoningValleySanitaryDistrict_0025.tif



26. OH_Trumbull_MahoningValleySanitaryDistrict_0026.tif



27. OH_Trumbull_MahoningValleySanitaryDistrict_0027.tif



28. OH_Trumbull_MahoningValleySanitaryDistrict_0028.tif



29. OH_Trumbull_MahoningValleySanitaryDistrict_0029.tif



30. OH_Trumbull_MahoningValleySanitaryDistrict_0030.tif



31. OH_Trumbull_MahoningValleySanitaryDistrict_0031.tif




32. OH_Trumbull_MahoningValleySanitaryDistrict_0032.tif



 ${\bf 33. \ OH_Trumbull_MahoningValleySanitaryDistrict_0033.tif}$



34. OH_Trumbull_MahoningValleySanitaryDistrict_0034.tif



 $35. \ OH_Trumbull_MahoningValleySanitaryDistrict_0035.tif$



36. OH_Trumbull_MahoningValleySanitaryDistrict_0036.tif



 ${\bf 37. \ OH_Trumbull_MahoningValleySanitaryDistrict_0037.tif}$



38. OH_Trumbull_MahoningValleySanitaryDistrict_0038.tif



39. OH_Trumbull_MahoningValleySanitaryDistrict_0039.tif



40. OH_Trumbull_MahoningValleySanitaryDistrict_0040.tif



41. OH_Trumbull_MahoningValleySanitaryDistrict_0041.tif



42. OH_Trumbull_MahoningValleySanitaryDistrict_0042.tif



43. OH_Trumbull_MahoningValleySanitaryDistrict_0043.tif



44. OH_Trumbull_MahoningValleySanitaryDistrict_0044.tif



45. OH_Trumbull_MahoningValleySanitaryDistrict_0045.tif



46. OH_Trumbull_MahoningValleySanitaryDistrict_0046.tif



47. OH_Trumbull_MahoningValleySanitaryDistrict_0047.tif



48. OH_Trumbull_MahoningValleySanitaryDistrict_0048.tif



49. OH_Trumbull_MahoningValleySanitaryDistrict_0049.tif



50. OH_Trumbull_MahoningValleySanitaryDistrict_0050.tif



49. OH_Trumbull_MahoningValleySanitaryDistrict_0049.tif



50. OH_Trumbull_MahoningValleySanitaryDistrict_0050.tif



51. OH_Trumbull_MahoningValleySanitaryDistrict_0051.tif



52. OH_Trumbull_MahoningValleySanitaryDistrict_0052.tif



53. OH_Trumbull_MahoningValleySanitaryDistrict_0053.tif



54. OH_Trumbull_MahoningValleySanitaryDistrict_0054.in



55. OH_Trumbull_MahoningValleySanitaryDistrict_0055.tif

09 Appendix III: Historic Photo Index

Recordation of the Head House, Trestle and Settling Basins 1-4 for Meander Water, Mahoning Valley Sanitary District (MSVD) Mineral Ridge, Ohio

Name of Property:

Mahoning Valley Sanitary District

City:

Mineral Ridge, Ohio

County:

Trumbull

State:

Ohio

Name of Photographer: Date of Photographs: Unknown c. 1931

Location of Original Files:

Mahoning Valley Sanitary Water District


1181 Ohltown McDonald Rd

Mineral Ridge, OH 44440-9322

Number of Photos:

18

- Archive # 489. Contract 29A. Camera at Southeast corner of Settling Basin #2, looking northwest. Taken Feb. 25, 1931.
- Archive #490. Contract 29A. Taken from west side of Settling Basin #1, on center line looking east. March. 20, 1931.
- Archive # 588. Contract 29. Camera at S.W. corner of Settling Basin 3, looking N.E. Aug. 17, 1931.
- Archive #589. Contract 29. Camera at S.E. corner of Settling Basin #2, looking N.W. August. 17, 1931.
- Archive #578. Contract 29. Cont. 29. Camera on north side of Head House, below chemical bins, looking NE across Settling Basin #3. July 22, 1931.
- Archive #590. Contract 29. Camera at N.W. corner of Settling Basin #1, looking N.E. Aug. 17, 1931.
- 62 Date and description unknown.
- 63 Archive #638. Camera at Flag Pole base, looking east at Head House. Dec. 1, 1931.
- Archive # 631. Contract 29. Camera 15 ft. east of Northeast corner of Filter Building, looking Southeast at Preliminary Treatment Works. Nov. 10, 1931.
- Archive # 635. Contract 29. Camera 100 feet southeast of Settling Basin #2, looking north. Nov. 10, 1931.
- 66 Archive # 640. Camera 40 feet east of S.E. corner of Pumping Station, looking N.E. Dec. 1, 1931.
- 67 Archive #686. Camera on train Tracks by Boiler House, looking west. Jan. 26, 1932.
- 68 Archive # 643. Contract. 29. Camera 15 feet east of west end of Railroad Trestle, looking east. Dec. 1, 1931.
- 69 Archive # 633. Contract 29. Mixing Chamber 3 & 4 railings. Nov. 10, 1931
- 70 Archive #717. Mixing Chamber 1& 2 railings. March 17, 1932.
- 71 Archive #606. Settling Basin #2. Sept. 22, 1931.
- 72 Archive #632. Contract 29. Settling Basin #1 from west side. Nov. 10, 1931.
- 73 Archive #703. Settling Basin 3 & 4. Feb. 24, 1932.



Mahoning Valley Sanitary District SETTLING SETTLING BASIN #3 BASIN #4 SETTLING SETTLING BASIN #1 BASIN #2 N Drawings Not to Scale Title: Historic Photo Key First Floor Plan Chambers, Murphy & Burge 43 E. Market St. Suite 201 Location: Mineral Ridge, Ohio Akron, Ohio 44308 Sketch Number: Job No. 11-17 Chambers, Murphy & Burge Phone: (330) 434-9300 PK-05 Fax: (330) 434-9331 Date: August 2011




56. OH_Trumbull_MahoningValleySanitaryDistrict_0056.tif



57. OH_Trumbull_MahoningValleySanitar/District_0057.tif



58. OH_Trumbull_MahoningValleySanitaryDistrict_0058.tif



59. OH_Trumbull_MahoningValleySanitaryDistrict_0059.tif



60. OH_Trumbull_MahoningValleySanitaryDistrict_0060.tif



61. OH_Trumbull_MahoningValleySanitaryDistrict_0061.tif